

# **SAMPLE KTHH Home Health Report**

#### **Exterior Inspection**

## 1. Roof Inspection

• **Condition:** The roof is approximately 12 years old and shows some signs of wear, particularly around the valleys where water drainage is crucial.

# Findings:

- Several shingles are beginning to curl, and there are small signs of granule loss on the south-facing side.
- Flashing around chimneys and vents shows early signs of corrosion.

# • Repair Recommendations:

- Replace damaged or missing shingles (3–4 shingles) to prevent water infiltration.
- o Reapply roofing sealant around flashing to prevent water damage and rust.

#### **Interior Inspection**

# 1. HVAC (Heating, Ventilation, and Air Conditioning) System

• **Condition:** The HVAC system is 10 years old and in good working order, though it requires regular maintenance.

## Findings:

- The air filter is clogged with dust and debris, reducing airflow efficiency.
- The thermostat calibration is slightly off (1–2 degrees).

# Repair Recommendations:

- o **Replace the air filter** immediately to improve airflow and efficiency.
- Recalibrate or replace the thermostat to ensure accurate temperature control.



 Schedule an HVAC tune-up to clean ducts and check the system's overall performance.

## Conclusion

This **KTTH Home Preservation Program** report provides a comprehensive inspection of both the **interior** and **exterior** of your home. The recommended repairs and improvements will help ensure your home remains safe, efficient, and in good condition for years to come.